



FPLF Pneumatic Vibrator



FAL Pneumatic Vibrator

The FPLF and FAL Pneumatic Vibrator should be dismantled every 1500 hours and the piston regreased with Kluber Grease UHI.14.31 This is available in a small tub part number 046757



VIBRATECHNIQUES LTD

20 Cecil Pashley Way, Shoreham Airport, Shoreham by Sea, West Sussex, BN43 5FF

Tel: +44 (0)1273 430977 Fax: +44 (0)1273 430978 Email: sales@vibtec.com Web: www.vibtec.com